

SITE INSPECTION REPORT

NSW GOVERNMENT
Planning & Infrastructure

24 MAR 2016

DEVELOPMENT ASSESSMENT AND
SYSTEMS PERFORMANCE
RECEIVED - JINDABYNE

Job No.

LOCATION: Aspen Creek #4, Thredbo, NSW
Inspection Stage: Foundation
Builder: Doug Barrett

Comments :

From a design check I can confirm that the existing footings are structurally adequate to support additional load from new structure.

Instructions:

Issued to: D Barrett

Inspected by: PIERRE DRAGH.

Copies to:

Date: 24-12-15

- * This document does not authorize any variation from the contract unless otherwise approved by the engineer.
- * This certificate does not relieve the responsibility of the builder/contractor from the performing work in accordance with the new line building Act/ordinance and approves documents/specifications.

PIERRE DRAGH
(MIE Aust, RPEQ)
CONSULTING ENGINEERS P
P.O. BOX 336
HALL ACT 2618
Ph: 0438 625 440
pdragh@bigpond.com
MIE AUST. 1158 352
RPEQ 5882