

Douglas Partners Pty Ltd ABN 75 053 980 117 www.douglaspartners.com.au Unit 2, 73 Sheppard Street Hume ACT 2620 PO Box 1487 Fyshwick ACT 2609 Phone (02) 6260 2788 Fax (02) 6260 1147

Kunapipi Ski Lodge Co-Operative Ltd PO Box 6275 Pymble NSW 2073

21 March 2018 R.001.Rev0 MJJ

Project 94004.00

Attention: Des Brady

Email: des9999@live.com.au

Dear Sirs

Proposed Access Ramp/Stairs and Deck Kunapipi Ski Lodge, Perisher Valley

As requested, the above site was visited by the writer on 16 March 2018 for the purposes of assessing the geotechnical implications (if any) of the proposed development at the site. It is understood that the construction of an additional access ramp/stairs and deck are proposed for the northern side of the existing building.

Site works as detailed on the Development Application DA 2A, drawing dated August 2017, prepared by Mark Cambourn and Associates Pty Ltd (see attached drawing) indicate that minimal site earthworks will be required and that the ramp/stairs and deck would be of galvanised steel similar to the ramp/stairs at the southern side of the lodge.

At the time of the inspection, the existing building was in good condition, and no signs of slope instability were observed within or adjacent to the development area. We note that a geotechnical risk assessment was conducted by Geotechnical Consultants in 2003 (Ref 1) which indicated a very low to low risk of slope instability.

It is concluded that the proposed development will have minimal geotechnical impact on site conditions from a stability perspective, and that the hazard risk level will not be increased by the works.

We would recommend that all footings must found within weathered rock and viewed by a Geotechnical Engineer to confirm the suitability of the founding stratum. Also, site surface drainage or any existing subsurface drainage systems must not be compromised by the proposed works.

This letter must be read in conjunction with the attached notes "About This inspection Report" A Form 4 "Minimal Impact Certification" report is also attached to this report. We trust the above is in accordance with your present requirements. If you have any questions please contact the undersigned.





Yours faithfully

Douglas Partners Pty Ltd

Reviewed by

Gary Renfrey
Senior Associate

Michael Jones Principal

Reference:

 Geotechnical Consultants Pty Ltd "Kunapipi Lodge, Perisher Valley, Alterations and Additions", dated 21 August 2003

Attachments:

About This Inspection Report

Form 4 Certificate

Site Plan

About this Inspection Report



Introduction

These notes are provided to amplify DP's inspection report in regard to the limitations of carrying out inspection work. Not all notes are necessarily relevant to this report.

Standards

This inspection report has been prepared by qualified personnel to current engineering standards of interpretation and analysis.

Copyright and Limits of Use

This inspection report is the property of DP and is provided for the exclusive use of the client for the specific project and purpose as described in the report. It should not be used by a third party for any purpose other than to confirm that the construction works addressed in the report have been inspected as described. Use of the inspection report is limited in accordance with the Conditions of Engagement for the commission.

DP does not undertake to guarantee the works of the contractors or relieve them of their responsibility to produce a completed product conforming to the design.

Reports

This inspection report may include advice or opinion that is based on engineering and/or geological interpretation, information provided by the client or the client's agent, and information gained from:

- an investigation report for the project (if available to DP);
- inspection of the work, exposed ground conditions, excavation spoil and performance of excavating equipment while DP was on site;
- investigation and testing that was carried out during the site inspection;
- anecdotal information provided by authoritative site personnel; and

DP's experience and knowledge of local geology.

Such information may be limited by the frequency of any inspection or testing that was able to be practically carried out, including possible site or cost constraints imposed by the client/contractor(s). For these reasons, the reliability of this inspection report is limited by the scope of information on which it relies.

Every care is taken with the inspection report as it relates to interpretation of subsurface conditions and any recommendations or suggestions for construction or design. However, DP cannot anticipate or assume responsibility for:

- unexpected variations in subsurface conditions that are not evident from the inspection; and
- the actions of contractors responding to commercial pressures.

Should these issues occur, then additional advice should be sought from DP and, if required, amendments made.

This inspection report must be read in conjunction with any attached information. This inspection report should be kept in its entirety without separation of individual pages or sections. DP cannot be held responsible for interpretations or conclusions from review by others of this inspection report or test data, which are not otherwise supported by an expressed statement, interpretation, outcome or conclusion stated in this inspection report.



Geotechnical Policy Kosciuszko Alpine Resorts

Page 1 of 2

Version: December 2015

Form 4 - Minimal Impact Certification

DA Number: _____

This form may be used where minor construction works which present minimal or no geotechnical impact on the site or related land are proposed to be erected within the "G" line area of the geotechnical maps.
A geotechnical engineer or engineering geologist must inspect the site and/or review the proposed development documentation to determine if the proposed development requires a geotechnical report to be prepared to accompany the development application. Where the geotechnical engineer determines that such a report is not required then they must complete this form and attach design recommendations where required. A copy of Form 4 with design recommendation, if required, must be submitted with the development application.
Please contact the Alpine Resorts Team in Jindabyne for further information - phone 02 6456 1733.
To complete this form, please place a cross in the appropriate boxes and complete all sections.
 Declaration made by geotechnical engineer or engineering geologist in relation to a nil or minimal geotechnical impact assessment and site classification
I, Mr
First Name Family Name
Michael Jones
Company/organisation Douslas Partners Pty Utd certify that I am a geotechnical engineer /engineering geologist as defined by the "Policy" and I have inspected the site and reviewed the proposed development known as Kunapipi SICI Lodge (Lot I DP 863582) Perisher Valley
ROMAPIPI SICI WASE (LOFT DE 865582) TETTET VALID
As a result of my site inspection and review of the following documentation (List of documentation reviewed)
Project Drawing Prepared by Maric Cambourn & Associates Aug 2017

ordance with this site classification are that this declaration shall be u	sed by the Department as an essential component in
ordance with this site classification are that this declaration shall be u	n. sed by the Department as an essential component in
are that this declaration shall be u	sed by the Department as an essential component in
eotechnical maps) of Kosciuszko	ure to be erected within the "G" line area (as identified Alpine Resorts without requiring the submission of a lopment application.
es	
	Chartered professional status
no	CPENG NER 1289811
	J Date
y Jones	21/3/2018
r	nical report in support of the deve

3. C

Alpine Resorts Team Shop 5A, 19 Snowy River Avenue P O Box 36, JINDABYNE NSW 2627 Telephone: 02 6456 1733

Facsimile: 02 6456 1736

alpineresorts@planning.nsw.gov.au Email:

